

Brian Quiros

From: Tisa, Kimberly
Sent: Thursday, November 3, 2016 2:45 PM
To: Mike Zarba
Cc: Gary Trombly; Tisa, Kimberly
Subject: FW: FW:
Attachments: IMG_1050.JPG; IMG_1049.JPG; IMG_1047.JPG; IMG_1045.JPG; IMG_1040.JPG

Mike:.

I am forwarding to you the information provided to EPA regarding the building demo work at CEC. I spoke with you about this on Monday but as yet have not heard anything from you.

As discussed, clarification on how these roofing materials and other C&D items are being managed is needed.

As you may recall, both CTDEEP and EPA discussed issues surrounding the concrete floor with you during our last site visit.

Both CTDEEP and I would like to discuss this matter further with you. Please propose time and date for our response.

Kimberly N. Tisa, PCB Coordinator
USEPA
5 Post Office Square, Suite 100
Boston, MA 02109-3912

617.918.1527 (phone)
617.918.0527 (fax)
Tisa.Kimberly@epa.gov

From: Insall, John [mailto:JInsall@partneresi.com]
Sent: Monday, October 31, 2016 4:39 PM
To: Tisa, Kimberly
Subject: FW: FW:

Kim – I have been asked by my client (Garcia & Milas) to forward these photos taken at the site this morning. Standard Demolition Services asks the following:

the roofing materials and other c&d items were stockpiled on the slab without a poly separation between the floor (which is considered remediation waste) and the roofing/ c&d materials. What happens to handling and disposal in that situation? Is the roofing / c&d now considered PCB contaminated because it is on the contaminated slab etc.? What is the EPA's position on that?

Thanks. John.

John Insall, LEP
National Client Manager









